
TE flaps
1
2
3
Three-hole probes
Payload bay
AoA1
AoA2
AoA3


100 % = 1.50 m
85 %
75 %
65 %
0.19
Zigzag tape
Pressure ports
Three-hole probes
Flaps
Strain gages
0.3c
0.1R
0.1R
0.1R