

Stacked bar chart showing the number of significant events for various parameters across different models. The y-axis is '# Significant Events' (0 to 400). The x-axis lists parameters: Root Bending Mom., Root Pitching Mom., LS Shaft Bending Mom., Yaw Yaw-bearing Bending Mom., Yaw-bearing Yaw Mom., Twr. Base Mom., Blade Tip Deflection, Fairlead Tension, Anchor Tension, Watch Circle, Heel Angle, Nacelle Acceleration, and Power. The legend includes SD VO, SD VR, SU VO, SU VR, SU VI, FT VO, FT VR, OP VO, OP VR, and OP VI.